

Flood Control Project Maintenance
2018 Structure Summary Report
Overall Unit and Item Ratings

San Joaquin County Flood Control and Water Conservation District

Duck Creek Diversion Weir And Control Structure

Overall Unit Rating	Rated Item	Item Rating
A	Photo Documentation	N
	Vegetation & Obstructions	A
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments	A
	Encroachments	A
	Culverts: Inlets / Outlets	M
	Culverts: Breaks / Holes / Cracks	A
	Metal Pipes	A
	Trash Racks	N
	Flap Gates	N
	Sluice/Slide Gates	M
	Electric Gate Operators	N
	Manual Gate Operators	A
	Concrete Surfaces	A
	Concrete Tilting / Settlement	A
	Concrete Foundations	A
	Security Fencing	N
	Closure Structures	N
	Trash Rakes	N
	Other Metallic Items	A
	Monolith Joints	A
	Safety	A
	Operation & Maintenance Manual	A

Flood Control Project Maintenance
2018 Structure Summary Report
Overall Unit and Item Ratings

San Joaquin County Flood Control and Water Conservation District (cont.)

Mormon Slough Pumping Plant No. 1

Overall Unit Rating	Rated Item	Item Rating
A	Operating Log	A
	Operation & Maintenance Manual	A
	Plant Building	A
	Communications	A
	Safety	A
	Cranes	N
	Pumps	A
	Power	A
	Motors, Engines, Fans & Gear Reducers	N
	Pump Control Systems	A
	Sumps/Wet Well	A
	Trash Racks	A
	Trash Rakes	N
	Sluice / Slide Gates	A
	Electric Gate Operators	N
	Manual Gate Operators	A
	Other Metallic Items	A
	Flap Gates	A
	Closure Structures	N
	Security Fencing	M
	Intake and Discharge Pipes	A

Mormon Slough Pumping Plant No. 2

Overall Unit Rating	Rated Item	Item Rating
A	Operating Log	A
	Operation & Maintenance Manual	A
	Plant Building	A
	Communications	A
	Safety	A
	Cranes	N
	Pumps	A
	Power	A
	Motors, Engines, Fans & Gear Reducers	A
	Pump Control Systems	A
	Sumps/Wet Well	A
	Trash Racks	A
	Trash Rakes	N
	Sluice / Slide Gates	M
	Electric Gate Operators	N
	Manual Gate Operators	A
	Other Metallic Items	A
	Flap Gates	A
	Closure Structures	N
	Security Fencing	A
	Intake and Discharge Pipes	A

Flood Control Project Maintenance
2018 Structure Summary Report
Overall Unit and Item Ratings

San Joaquin County Flood Control and Water Conservation District (cont.)

Mormon Slough Pumping Plant No. 3

Overall Unit Rating	Rated Item	Item Rating
A	Operating Log	A
	Operation & Maintenance Manual	A
	Plant Building	A
	Communications	A
	Safety	A
	Cranes	N
	Pumps	A
	Power	A
	Motors, Engines, Fans & Gear Reducers	A
	Pump Control Systems	A
	Sumps/Wet Well	A
	Trash Racks	A
	Trash Rakes	N
	Sluice / Slide Gates	A
	Electric Gate Operators	N
	Manual Gate Operators	A
	Other Metallic Items	A
	Flap Gates	A
	Closure Structures	N
	Security Fencing	M
	Intake and Discharge Pipes	A

Flood Control Project Maintenance**Unit Cover Sheet****2018 Structure Inspection Results****San Joaquin County Flood Control and Water Conservation District**

Structure
Duck Creek Diversion Weir And Control Structure

Structure Rating	A
Date of Inspection	6/21/2018
DWR Inspector	Dave Torres
Accompanied By	Jim Caruso San Joaquin County

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Structure 2018

San Joaquin County Flood Control and Water Conservation District

Structure	Structure Length	Inspection Start/End	Inspector
Duck Creek Diversion Weir And Control Structure		06/21/2018 06/21/2018	Dave Torres

LM Start	0.00	Rating **	N	Issue No.	24
LM End	0.00	Issue Type +	Ma	Location *	
Category	Structures & Concrete Lined Channels			GPS Latitude/Longitude	
				Start	End
Item	Photo Documentation			37.938383 °	37.938383 °
				-120.990133 °	-120.990133 °
DWR ID	DWR_NA0017_5_t_2013_24				
Action/Comments					
Inspector Comments: Duck Creek Diversion Structure works as a control weir for Duck Creek and also diverts the overflow of the channel to Duck Creek Diversion channel which connects with Little John Creek.					

Photo 1 of 2 : ST_2018_NA0017_5_24_20180625_00019.jpg



View of the weir. Summer 2018

LM Start	0.00	Rating **	N	Issue No.	24 (cont)
LM End	0.00	Issue Type +	Ma	Location *	

Photo 2 of 2 : ST_2018_NA0017_5_24_20180530_00012.jpg



View of the weir.

LM Start	0.00	Rating **	A	Issue No.	2
LM End	0.00	Issue Type +	Ma	Location *	
Category	Structures & Concrete Lined Channels			GPS Latitude/Longitude	
				Start	End
Item	Vegetation & Obstructions			37.938383 °	37.938383 °
				-120.990133 °	-120.990133 °
DWR ID	DWR_NA0017_5_t_2012_2				
Action/Comments					
Inspector Comments: There was minimal vegetation with new cat tails growth on the upstream side of the weir with minimal potential to impede flow.					

Photo 1 of 2 : ST_2018_NA0017_5_2_20180625_00013.jpg



View of the vegetation looking upstream of the weir. Summer 2018

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Structure 2018

San Joaquin County Flood Control and Water Conservation District

Structure	Structure Length	Inspection Start/End	Inspector
Duck Creek Diversion Weir And Control Structure		06/21/2018 06/21/2018	Dave Torres

LM Start	0.00	Rating **	A	Issue No.	2 (cont)	
LM End	0.00	Issue Type +	Ma	Location *		
Category	Structures & Concrete Lined Channels			GPS Latitude/Longitude		
				Start		End
Item	Vegetation & Obstructions			37.938383 °		37.938383 °
				-120.990133 °		-120.990133 °
DWR ID	DWR_NA0017_5_t_2012_2					
Action/Comments						
Inspector Comments: There was minimal vegetation with new cat tails growth on the upstream side of the weir with minimal potential to impede flow.						

Photo 2 of 2 : ST_2018_NA0017_5_2_20180530_00001.jpg



View of the vegetation looking upstream of the weir. Summer 2017

LM Start	0.00	Rating **	A	Issue No.	3
LM End	0.00	Issue Type +	Ma	Location *	
Category	Structures & Concrete Lined Channels	GPS Latitude/Longitude			
		Start		End	
Item	Shoaling / Sedimentation	37.938383 °		37.938383 °	
		-120.990133 °		-120.990133 °	
DWR ID	DWR_NA0017_5_t_2012_3				
Action/Comments					
Inspector Comments: No shoaling or sediment was present.					

No Photos

LM Start	0.00	Rating **	A	Issue No.	4
LM End	0.00	Issue Type +	Ma	Location *	
Category	Structures & Concrete Lined Channels	GPS Latitude/Longitude			
		Start		End	
Item	Erosion / Bank Caving	37.938383 °		37.938383 °	
		-120.990133 °		-120.990133 °	
DWR ID	DWR_NA0017_5_t_2012_4				
Action/Comments					
Inspector Comments: No erosion or bank caving was observed.					

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Structure 2018

San Joaquin County Flood Control and Water Conservation District

Structure	Structure Length	Inspection Start/End	Inspector
Duck Creek Diversion Weir And Control Structure		06/21/2018 06/21/2018	Dave Torres

LM Start	0.00	Rating **	A	Issue No.	5
LM End	0.00	Issue Type +	Ma	Location *	
Category	Structures & Concrete Lined Channels			GPS Latitude/Longitude	
				Start	End
Item	Revetments			37.938383 °	37.938383 °
				-120.990133 °	-120.990133 °
DWR ID	DWR_NA0017_5_t_2012_5				
Action/Comments					
Inspector Comments: Existing riprap protection was properly maintained.					

Photo 1 of 2 : ST_2018_NA0017_5_5_20180530_00002.jpg



View of the revetments looking downstream of the weir.

LM Start	0.00	Rating **	A	Issue No.	5 (cont)
LM End	0.00	Issue Type +	Ma	Location *	

Photo 2 of 2 : ST_2018_NA0017_5_5_20180530_00003.jpg



View of the revetments looking upstream of the weir.

LM Start	0.00	Rating **	A	Issue No.	6
LM End	0.00	Issue Type +	Ma	Location *	
Category	Structures & Concrete Lined Channels			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			37.938383 °	37.938383 °
				-120.990133 °	-120.990133 °
DWR ID	DWR_NA0017_5_t_2012_6				
Action/Comments					
Inspector Comments: No trash or debris were found around the structure.					

No Photos

*** Location**
LS : Land Side
WS : Water Side
CR : Crown

**** Rating**
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Structure 2018

San Joaquin County Flood Control and Water Conservation District

Structure	Structure Length	Inspection Start/End	Inspector
Duck Creek Diversion Weir And Control Structure		06/21/2018 06/21/2018	Dave Torres

LM Start	0.00	Rating **	M	Issue No.	7
LM End	0.00	Issue Type +	Ma	Location *	
Category	Structures & Concrete Lined Channels			GPS Latitude/Longitude	
				Start	End
Item	Culverts: Inlets / Outlets			37.938383 °	37.938383 °
				-120.990133 °	-120.990133 °
DWR ID	DWR_NA0017_5_t_2012_7				
Action/Comments					
Inspector Comments: The culvert's inlet had minor debris that should be cleared and the outlet were free of any debris.					

Photo 1 of 2 : ST_2018_NA0017_5_7_20180625_00014.jpg



View of the inlet of the culvert. 2018

LM Start	0.00	Rating **	M	Issue No.	7 (cont)
LM End	0.00	Issue Type +	Ma	Location *	

Photo 2 of 2 : ST_2018_NA0017_5_7_20180625_00015.jpg



View of the outlet of the culvert. 2018

LM Start	0.00	Rating **	A	Issue No.	8
LM End	0.00	Issue Type +	Ma	Location *	
Category	Structures & Concrete Lined Channels			GPS Latitude/Longitude	
				Start	End
Item	Culverts: Breaks / Holes / Cracks			37.938383 °	37.938383 °
				-120.990133 °	-120.990133 °
DWR ID	DWR_NA0017_5_t_2012_8				
Action/Comments					
Inspector Comments: No visible cracks or holes were found that would result in significant water leakage in the culvert.					

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Structure 2018

San Joaquin County Flood Control and Water Conservation District

Structure	Structure Length	Inspection Start/End	Inspector
Duck Creek Diversion Weir And Control Structure		06/21/2018 06/21/2018	Dave Torres

LM Start	0.00	Rating **	A	Issue No.	9
LM End	0.00	Issue Type +	Ma	Location *	
Category	Structures & Concrete Lined Channels	GPS Latitude/Longitude			
		Start		End	
Item	Metal Pipes	37.938383 °		37.938383 °	
		-120.990133 °		-120.990133 °	
DWR ID	DWR_NA0017_5_t_2012_9				
Action/Comments					
Inspector Comments: The corrugated pipes inside the culvert appeared to be in good condition.					

No Photos

LM Start	0.00	Rating **	N	Issue No.	10
LM End	0.00	Issue Type +	Ma	Location *	
Category	Structures & Concrete Lined Channels			GPS Latitude/Longitude	
				Start	End
Item	Trash Racks			37.938383 °	37.938383 °
				-120.990133 °	-120.990133 °
DWR ID	DWR_NA0017_5_t_2012_10				
Action/Comments					
Inspector Comments: This item does not apply to this inspection.					

No Photos

LM Start	0.00	Rating **	N	Issue No.	11	
LM End	0.00	Issue Type +	Ma	Location *		
Category	Structures & Concrete Lined Channels			GPS Latitude/Longitude		
				Start		End
Item	Flap Gates			37.938383 °		37.938383 °
				-120.990133 °		-120.990133 °
DWR ID	DWR_NA0017_5_t_2012_11					
Action/Comments						
Inspector Comments: No flap gates were present at this structure.						

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Structure 2018

San Joaquin County Flood Control and Water Conservation District

Structure	Structure Length	Inspection Start/End	Inspector
Duck Creek Diversion Weir And Control Structure		06/21/2018 06/21/2018	Dave Torres

LM Start	0.00	Rating **	M	Issue No.	12	
LM End	0.00	Issue Type +	Ma	Location *		
Category	Structures & Concrete Lined Channels			GPS Latitude/Longitude		
				Start		End
Item	Sluice/Slide Gates			37.938383 °	37.938383 °	
				-120.990133 °	-120.990133 °	
DWR ID	DWR_NA0017_5_t_2012_12					
Action/Comments						
Inspector Comments: The gates appeared to be in good working condition. The screw gate needs to be maintained properly so that it can be turned with ease.						

Photo 1 of 1 : ST_2018_NA0017_5_12_20180625_00016.jpg



View of the slide gate. Summer 2018

LM Start	0.00	Rating **	N	Issue No.	13
LM End	0.00	Issue Type +	Ma	Location *	
Category	Structures & Concrete Lined Channels			GPS Latitude/Longitude	
				Start	End
Item	Electric Gate Operators			37.938383 °	37.938383 °
				-120.990133 °	-120.990133 °
DWR ID	DWR_NA0017_5_t_2012_13				
Action/Comments					
Inspector Comments: No electric gate operator was found at this structure.					

No Photos

LM Start	0.00	Rating **	A	Issue No.	14
LM End	0.00	Issue Type +	Ma	Location *	
Category	Structures & Concrete Lined Channels			GPS Latitude/Longitude	
				Start	End
Item	Manual Gate Operators			37.938383 °	37.938383 °
				-120.990133 °	-120.990133 °
DWR ID	DWR_NA0017_5_t_2012_14				
Action/Comments					
Inspector Comments: The manual gate appeared to be operational.					

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Structure 2018

San Joaquin County Flood Control and Water Conservation District

Structure	Structure Length	Inspection Start/End	Inspector
Duck Creek Diversion Weir And Control Structure		06/21/2018 06/21/2018	Dave Torres

LM Start	0.00	Rating **	A	Issue No.	15
LM End	0.00	Issue Type +	Ma	Location *	
Category	Structures & Concrete Lined Channels			GPS Latitude/Longitude	
				Start	End
Item	Concrete Surfaces			37.938383 °	37.938383 °
				-120.990133 °	-120.990133 °
DWR ID	DWR_NA0017_5_t_ 2012_15				
Action/Comments					
Inspector Comments: The concrete surfaces had minor cracking and the surface was weathered but they didn't pose any threats to the integrity of the structure.					

Photo 1 of 2 : ST_2018_NA0017_5_15_20180625_00017.jpg



View of the weir and the concrete surface during 2018 inspection.

Photo 2 of 2 : ST_2018_NA0017_5_15_20180530_00008.jpg



View of the weir and the concrete surface during 2017 inspection.

LM Start	0.00	Rating **	A	Issue No.	15 (cont)
LM End	0.00	Issue Type +	Ma	Location *	

LM Start	0.00	Rating **	A	Issue No.	16
LM End	0.00	Issue Type +	Ma	Location *	
Category	Structures & Concrete Lined Channels			GPS Latitude/Longitude	
				Start	End
Item	Concrete Tilting / Settlement			37.938383 °	37.938383 °
				-120.990133 °	-120.990133 °
DWR ID	DWR_NA0017_5_t_ 2012_16				
Action/Comments					
Inspector Comments: No visible sliding or settlement was found on the structure.					

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Structure 2018

San Joaquin County Flood Control and Water Conservation District

Structure	Structure Length	Inspection Start/End	Inspector
Duck Creek Diversion Weir And Control Structure		06/21/2018 06/21/2018	Dave Torres

LM Start	0.00	Rating **	A	Issue No.	17
LM End	0.00	Issue Type +	Ma	Location *	
Category	Structures & Concrete Lined Channels			GPS Latitude/Longitude	
				Start	End
Item	Concrete Foundations			37.938383 °	37.938383 °
				-120.990133 °	-120.990133 °
DWR ID	DWR_NA0017_5_t_2012_17				
Action/Comments					
Inspector Comments: No scouring or erosion was found near the structure.					

No Photos

LM Start	0.00	Rating **	N	Issue No.	18
LM End	0.00	Issue Type +	Ma	Location *	
Category	Structures & Concrete Lined Channels			GPS Latitude/Longitude	
				Start	End
Item	Security Fencing			37.938383 °	37.938383 °
				-120.990133 °	-120.990133 °
DWR ID	DWR_NA0017_5_t_2012_18				
Action/Comments					
Inspector Comments: No security fence was found in this structure.					

No Photos

LM Start	0.00	Rating **	N	Issue No.	19
LM End	0.00	Issue Type +	Ma	Location *	
Category	Structures & Concrete Lined Channels			GPS Latitude/Longitude	
				Start	End
Item	Closure Structures			37.938383 °	37.938383 °
				-120.990133 °	-120.990133 °
DWR ID	DWR_NA0017_5_t_2012_19				
Action/Comments					
Inspector Comments: This item does not apply to this inspection.					

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Structure 2018

San Joaquin County Flood Control and Water Conservation District

Structure	Structure Length	Inspection Start/End	Inspector
Duck Creek Diversion Weir And Control Structure		06/21/2018 06/21/2018	Dave Torres

LM Start	0.00	Rating **	N	Issue No.	20
LM End	0.00	Issue Type +	Ma	Location *	
Category	Structures & Concrete Lined Channels	GPS Latitude/Longitude			
		Start		End	
Item	Trash Rakes	37.938383 °		37.938383 °	
		-120.990133 °		-120.990133 °	
DWR ID	DWR_NA0017_5_t_2012_20				
Action/Comments					
Inspector Comments: Trash rakes don't exist on this structure.					

No Photos

LM Start	0.00	Rating **	A	Issue No.	21
LM End	0.00	Issue Type +	Ma	Location *	
Category	Structures & Concrete Lined Channels	GPS Latitude/Longitude			
		Start		End	
Item	Other Metallic Items	37.938383 °		37.938383 °	
		-120.990133 °		-120.990133 °	
DWR ID	DWR_NA0017_5_t_2012_21				
Action/Comments					
Inspector Comments: All metal parts appeared to be in good condition.					

No Photos

LM Start	0.00	Rating **	A	Issue No.	22
LM End	0.00	Issue Type +	Ma	Location *	
Category	Structures & Concrete Lined Channels			GPS Latitude/Longitude	
				Start	End
Item	Monolith Joints			37.938383 °	37.938383 °
				-120.990133 °	-120.990133 °
DWR ID	DWR_NA0017_5_t_2012_22				
Action/Comments					
Inspector Comments: All the monolith joint materials appeared to be in good condition.					

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Structure 2018

San Joaquin County Flood Control and Water Conservation District

Structure	Structure Length	Inspection Start/End	Inspector
Duck Creek Diversion Weir And Control Structure		06/21/2018 06/21/2018	Dave Torres

LM Start	0.00	Rating **	A	Issue No.	23
LM End	0.00	Issue Type +	Ma	Location *	
Category	Structures & Concrete Lined Channels	GPS Latitude/Longitude			
		Start		End	
Item	Safety	37.938383 °		37.938383 °	
		-120.990133 °		-120.990133 °	
DWR ID	DWR_NA0017_5_t_2012_23				
Action/Comments					
Inspector Comments: The wood railing top of the culvert appeared to provide adequate protection against fall hazards.					

Photo 1 of 2 : ST_2018_NA0017_5_23_20180625_00018.jpg



View of the railing on the top of the inlet culvert.

LM Start	0.00	Rating **	A	Issue No.	23 (cont)
LM End	0.00	Issue Type +	Ma	Location *	

Photo 2 of 2 : ST_2018_NA0017_5_23_20180530_00010.jpg



View of the fence at the outlet of the structure.

LM Start	0.00	Rating **	A	Issue No.	1
LM End	0.00	Issue Type +	Ma	Location *	
Category	Structures & Concrete Lined Channels	GPS Latitude/Longitude			
		Start		End	
Item	Operation & Maintenance Manual	37.938383 °		37.938383 °	
		-120.990133 °		-120.990133 °	
DWR ID	DWR_NA0017_5_t_2013_1				
Action/Comments					
Inspector Comments: The LMA has the proper O&M manuals at their office.					

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

Flood Control Project Maintenance**Unit Cover Sheet****2018 Pumping Plant Inspection Results****San Joaquin County Flood Control and Water Conservation District**

Pumping Plant
Mormon Slough Pumping Plant No. 1

Pumping Plant Rating	A
Date of Inspection	6/21/2018
DWR Inspector	Dave Torres
Accompanied By	Jim Caruso San Joaquin County Channel Maintenance

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Structure 2018

San Joaquin County Flood Control and Water Conservation District

Structure	Structure Length	Inspection Start/End	Inspector
Mormon Slough Pumping Plant No. 1		06/21/2018 06/21/2018	Dave Torres

LM Start	0.00	Rating **	A	Issue No.	1
LM End	0.00	Issue Type +	Ma	Location *	
Category	Pump Stations			GPS Latitude/Longitude	
				Start	End
Item	Operating Log			37.989633 °	37.989633 °
				-121.266933 °	-121.266933 °
DWR ID	DWR_NA0017_18_t_2012_1				
Action/Comments					
Inspector Comments: Operating log was maintained and present at the pumping plant.					

Photo 1 of 1 : ST_2018_NA0017_18_1_20180625_00020.jpg



View of the operation log in the plant.

LM Start	0.00	Rating **	A	Issue No.	2
LM End	0.00	Issue Type +	Ma	Location *	
Category	Pump Stations			GPS Latitude/Longitude	
				Start	End
Item	Operation & Maintenance Manual			37.989633 °	37.989633 °
				-121.266933 °	-121.266933 °
DWR ID	DWR_NA0017_18_t_2012_2				
Action/Comments					
Inspector Comments: The O&M Manual was missing due to recent vandalism. The office has another copy of O&M manual.					

No Photos

LM Start	0.00	Rating **	A	Issue No.	3
LM End	0.00	Issue Type +	Ma	Location *	
Category	Pump Stations			GPS Latitude/Longitude	
				Start	End
Item	Plant Building			37.989633 °	37.989633 °
				-121.266933 °	-121.266933 °
DWR ID	DWR_NA0017_18_t_2012_3				
Action/Comments					
Inspector Comments: The plant building was in good structural condition.					

Photo 1 of 1 : ST_2018_NA0017_18_3_20180625_00016.jpg



View of the pumping plant.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Structure 2018

San Joaquin County Flood Control and Water Conservation District

Structure	Structure Length	Inspection Start/End	Inspector
Mormon Slough Pumping Plant No. 1		06/21/2018 06/21/2018	Dave Torres

LM Start	0.00	Rating **	A	Issue No.	4
LM End	0.00	Issue Type +	Ma	Location *	
Category	Pump Stations			GPS Latitude/Longitude	
				Start	End
Item	Communications			37.989633 °	37.989633 °
				-121.266933 °	-121.266933 °
DWR ID	DWR_NA0017_18_t_2012_4				
Action/Comments					
Inspector Comments: District personnel carry cell phones and radios for communication.					

No Photos

LM Start	0.00	Rating **	A	Issue No.	5	
LM End	0.00	Issue Type +	Ma	Location *		
Category	Pump Stations			GPS Latitude/Longitude		
				Start	End	
Item	Safety			37.989633	37.989633	
				-121.266933	-121.266933	
DWR ID	DWR_NA0017_18_t_2012_5					
Action/Comments						
Inspector Comments: There were no safety hazards found around the structure and the guard rails around the structure were in good condition.						

Photo 1 of 1 : ST_2018_NA0017_18_5_20180625_00017.jpg



View of the guard rails around the plant.

LM Start	0.00	Rating **	N	Issue No.	6	
LM End	0.00	Issue Type +	Ma	Location *		
Category	Pump Stations			GPS Latitude/Longitude		
				Start		End
Item	Cranes			37.989633 °		37.989633 °
				-121.266933 °		-121.266933 °
DWR ID	DWR_NA0017_18_t_2012_6					
Action/Comments						
Inspector Comments: No crane was present at this plant.						

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Structure 2018

San Joaquin County Flood Control and Water Conservation District

Structure	Structure Length	Inspection Start/End	Inspector
Mormon Slough Pumping Plant No. 1		06/21/2018 06/21/2018	Dave Torres

LM Start	0.00	Rating **	A	Issue No.	7
LM End	0.00	Issue Type +	Ma	Location *	
Category	Pump Stations			GPS Latitude/Longitude	
				Start	End
Item	Pumps			37.989633 °	37.989633 °
				-121.266933 °	-121.266933 °
DWR ID	DWR_NA0017_18_t_2012_7				
Action/Comments					
Inspector Comments: All pumps appeared to be in working condition and they were maintained, lubricated and tested periodically.					

Photo 1 of 2 : ST_2018_NA0017_18_7_20180625_00018.jpg



View of the pumps inside the plant.

LM Start	0.00	Rating **	A	Issue No.	7 (cont)
LM End	0.00	Issue Type +	Ma	Location *	

Photo 2 of 2 : ST_2018_NA0017_18_7_20180530_00006.jpg



View of the shaft under a pump.

LM Start	0.00	Rating **	A	Issue No.	8
LM End	0.00	Issue Type +	Ma	Location *	
Category	Pump Stations	GPS Latitude/Longitude			
		Start	End		
Item	Power	37.989633 °		37.989633 °	
		-121.266933 °		-121.266933 °	
DWR ID	DWR_NA0017_18_t_2012_8				
Action/Comments					
Inspector Comments: The power source appeared to be safe and reliable.					

Photo 1 of 1 : ST_2018_NA0017_18_8_20180625_00019.jpg



View of the power source next to the pumping plant.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Structure 2018

San Joaquin County Flood Control and Water Conservation District

Structure	Structure Length	Inspection Start/End	Inspector
Mormon Slough Pumping Plant No. 1		06/21/2018 06/21/2018	Dave Torres

LM Start	0.00	Rating **	N	Issue No.	10
LM End	0.00	Issue Type +	Ma	Location *	
Category	Pump Stations			GPS Latitude/Longitude	
				Start	End
Item	Motors, Engines, Fans & Gear Reducers			37.989633 °	37.989633 °
				-121.266933 °	-121.266933 °
DWR ID	DWR_NA0017_18_t_2012_10				
Action/Comments					

No Photos

LM Start	0.00	Rating **	A	Issue No.	11
LM End	0.00	Issue Type +	Ma	Location *	
Category	Pump Stations			GPS Latitude/Longitude	
				Start	End
Item	Pump Control Systems			37.989633 °	37.989633 °
				-121.266933 °	-121.266933 °
DWR ID	DWR_NA0017_18_t_2012_11				
Action/Comments					
Inspector Comments: The pump control systems were maintained properly and appeared to be free of damage even though vandalism has occurred inside the plant building.					


Photo 1 of 1 : ST_2018_NA0017_18_11_20180625_00021.jpg



View of the pump control system inside the plant.

LM Start	0.00	Rating **	A	Issue No.	12
LM End	0.00	Issue Type +	Ma	Location *	
Category	Pump Stations			GPS Latitude/Longitude	
				Start	End
Item	Sumps/Wet Well			37.989633 °	37.989633 °
				-121.266933 °	-121.266933 °
DWR ID	DWR_NA0017_18_t_2012_12				
Action/Comments					
Inspector Comments: The wet well was completely dry and very little debris was present during inspection.					

Photo 1 of 1 : ST_2018_NA0017_18_12_20180625_00022.jpg



View of the wet well.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Structure 2018

San Joaquin County Flood Control and Water Conservation District

Structure	Structure Length	Inspection Start/End	Inspector
Mormon Slough Pumping Plant No. 1		06/21/2018 06/21/2018	Dave Torres

LM Start	0.00	Rating **	A	Issue No.	13
LM End	0.00	Issue Type +	Ma	Location *	
Category	Pump Stations			GPS Latitude/Longitude	
				Start	End
Item	Trash Racks			37.989633 °	37.989633 °
				-121.266933 °	-121.266933 °
DWR ID	DWR_NA0017_18_t_2012_13				
Action/Comments					
Inspector Comments: Trash racks were properly maintained and clear of debris.					

Photo 1 of 1 : ST_2018_NA0017_18_13_20180625_00023.jpg



View of the trash racks.

LM Start	0.00	Rating **	N	Issue No.	14	
LM End	0.00	Issue Type +	Ma	Location *		
Category	Pump Stations			GPS Latitude/Longitude		
				Start	End	
Item	Trash Rakes			37.989633 °	37.989633 °	
				-121.266933 °	-121.266933 °	
DWR ID	DWR_NA0017_18_t_2012_14					
Action/Comments						
Inspector Comments: Trash rakes don't exist at this plant.						

No Photos

LM Start	0.00	Rating **	A	Issue No.	15
LM End	0.00	Issue Type +	Ma	Location *	
Category	Pump Stations			GPS Latitude/Longitude	
				Start	End
Item	Sluice / Slide Gates			37.989633 °	37.989633 °
				-121.266933 °	-121.266933 °
DWR ID	DWR_NA0017_18_t_2012_15				
Action/Comments					
Inspector Comments: The slide gate appeared to be in good condition. The wheel was removed for safety/security purposes.					

Photo 1 of 1 : ST_2018_NA0017_18_15_20180625_00024.jpg



View of the slide gate.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Structure 2018

San Joaquin County Flood Control and Water Conservation District

Structure	Structure Length	Inspection Start/End	Inspector
Mormon Slough Pumping Plant No. 1		06/21/2018 06/21/2018	Dave Torres

LM Start	0.00	Rating **	N	Issue No.	16
LM End	0.00	Issue Type +	Ma	Location *	
Category	Pump Stations			GPS Latitude/Longitude	
				Start	End
Item	Electric Gate Operators			37.989633 °	37.989633 °
				-121.266933 °	-121.266933 °
DWR ID	DWR_NA0017_18_t_2012_16				
Action/Comments					
Inspector Comments: The item does not apply to the pumping plant.					

No Photos

LM Start	0.00	Rating **	A	Issue No.	17
LM End	0.00	Issue Type +	Ma	Location *	
Category	Pump Stations			GPS Latitude/Longitude	
				Start	End
Item	Manual Gate Operators			37.989633 °	37.989633 °
				-121.266933 °	-121.266933 °
DWR ID	DWR_NA0017_18_t_2012_17				
Action/Comments					
Inspector Comments: Manual gate operator was in good operational condition.					

No Photos

LM Start	0.00	Rating **	A	Issue No.	18	
LM End	0.00	Issue Type +	Ma	Location *		
Category	Pump Stations			GPS Latitude/Longitude		
				Start	End	
Item	Other Metallic Items			37.989633 °	37.989633 °	
				-121.266933 °	-121.266933 °	
DWR ID	DWR_NA0017_18_t_2012_18					
Action/Comments						
Inspector Comments: All metal parts appeared to be in good condition.						

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Structure 2018

San Joaquin County Flood Control and Water Conservation District

Structure	Structure Length	Inspection Start/End	Inspector
Mormon Slough Pumping Plant No. 1		06/21/2018 06/21/2018	Dave Torres

LM Start	0.00	Rating **	A	Issue No.	19
LM End	0.00	Issue Type +	Ma	Location *	
Category	Pump Stations			GPS Latitude/Longitude	
				Start	End
Item	Flap Gates			37.989633 °	37.989633 °
				-121.266933 °	-121.266933 °
DWR ID	DWR_NA0017_18_t_2012_19				
Action/Comments					
Inspector Comments: The flap gates appeared to be in good working condition.					

Photo 1 of 2 : ST_2018_NA0017_18_19_20180625_00025.jpg



View of the flap gates during 2018 inspection.

LM Start	0.00	Rating **	A	Issue No.	19 (cont)
LM End	0.00	Issue Type +	Ma	Location *	

Photo 2 of 2 : ST_2018_NA0017_18_19_20180530_00013.jpg



View of the flap gates during 2017 inspection.

LM Start	0.00	Rating **	N	Issue No.	20
LM End	0.00	Issue Type +	Ma	Location *	
Category	Pump Stations			GPS Latitude/Longitude	
				Start	End
Item	Closure Structures			37.989633 °	37.989633 °
				-121.266933 °	-121.266933 °
DWR ID	DWR_NA0017_18_t_2012_20				
Action/Comments					
Inspector Comments: No closure structure was present at this plant.					

No Photos

*** Location**
LS : Land Side
WS : Water Side
CR : Crown

**** Rating**
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Structure 2018

San Joaquin County Flood Control and Water Conservation District

Structure	Structure Length	Inspection Start/End	Inspector
Mormon Slough Pumping Plant No. 1		06/21/2018 06/21/2018	Dave Torres

LM Start	0.00	Rating **	M	Issue No.	21
LM End	0.00	Issue Type +	Ma	Location *	
Category	Pump Stations			GPS Latitude/Longitude	
				Start	End
Item	Security Fencing			37.989633 °	37.989633 °
				-121.266933 °	-121.266933 °
DWR ID	DWR_NA0017_18_t_2012_21				
Action/Comments					
Inspector Comments: Part of the security fencing was missing due to recent vandalism. But, the plant building is secured. LMA has replaced fence within the past year and it was removed again.					

Photo 1 of 2 : ST_2018_NA0017_18_21_20180625_00026.jpg



View of missing fence links next to the pumping plant. Summer 2018

LM Start	0.00	Rating **	M	Issue No.	21 (cont)
LM End	0.00	Issue Type +	Ma	Location *	

Photo 2 of 2 : ST_2018_NA0017_18_21_20180530_00015.jpg



View of missing fence links next to the pumping plant. Summer 2017

LM Start	0.00	Rating **	A	Issue No.	22
LM End	0.00	Issue Type +	Ma	Location *	
Category	Pump Stations			GPS Latitude/Longitude	
				Start	End
Item	Intake and Discharge Pipes			37.989633 °	37.989633 °
				-121.266933 °	-121.266933 °
DWR ID	DWR_NA0017_18_t_2012_22				
Action/Comments					
Inspector Comments: The pipes appeared to be in good working condition.					

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

Flood Control Project Maintenance**Unit Cover Sheet****2018 Pumping Plant Inspection Results****San Joaquin County Flood Control and Water Conservation District**

Pumping Plant
Mormon Slough Pumping Plant No. 2

Pumping Plant Rating	A
Date of Inspection	6/21/2018
DWR Inspector	Dave Torres
Accompanied By	Jim Caruso San Joaquin County Channel Maintenance

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Structure 2018

San Joaquin County Flood Control and Water Conservation District

Structure	Structure Length	Inspection Start/End	Inspector
Mormon Slough Pumping Plant No. 2		06/21/2018 06/21/2018	Dave Torres

LM Start	0.00	Rating **	A	Issue No.	1
LM End	0.00	Issue Type +	Ma	Location *	
Category	Pump Stations			GPS Latitude/Longitude	
				Start	End
Item	Operating Log			37.982317 °	37.982317 °
				-121.249433 °	-121.249433 °
DWR ID	DWR_NA0017_19_t_2012_1				
Action/Comments					
Inspector Comments: Operational log was present at the pump station.					

Photo 1 of 1 : ST_2018_NA0017_19_1_20180625_00015.jpg



View of the operation log inside the pumping plant.

LM Start	0.00	Rating **	A	Issue No.	2
LM End	0.00	Issue Type +	Ma	Location *	
Category	Pump Stations			GPS Latitude/Longitude	
				Start	End
Item	Operation & Maintenance Manual			37.982317 °	37.982317 °
				-121.249433 °	-121.249433 °
DWR ID	DWR_NA0017_19_t_2012_2				
Action/Comments					
Inspector Comments: O&M Manual was found inside the plant during the inspection.					

Photo 1 of 1 : ST_2018_NA0017_19_2_20180625_00016.jpg



View of the O&M manual inside the plant.

LM Start	0.00	Rating **	A	Issue No.	3
LM End	0.00	Issue Type +	Ma	Location *	
Category	Pump Stations			GPS Latitude/Longitude	
				Start	End
Item	Plant Building			37.982317 °	37.982317 °
				-121.249433 °	-121.249433 °
DWR ID	DWR_NA0017_19_t_2012_3				
Action/Comments					
Inspector Comments: The plant building was in good structural condition without any major deficiencies.					

Photo 1 of 1 : ST_2018_NA0017_19_3_20180625_00017.jpg



View of the pumping plant.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Structure 2018

San Joaquin County Flood Control and Water Conservation District

Structure	Structure Length	Inspection Start/End	Inspector
Mormon Slough Pumping Plant No. 2		06/21/2018 06/21/2018	Dave Torres

LM Start	0.00	Rating **	A	Issue No.	4
LM End	0.00	Issue Type +	Ma	Location *	
Category	Pump Stations			GPS Latitude/Longitude	
				Start	End
Item	Communications			37.982317 °	37.982317 °
				-121.249433 °	-121.249433 °
DWR ID	DWR_NA0017_19_t_2012_4				
Action/Comments					
Inspector Comments: District personnel carry cell phones and radios.					

No Photos

LM Start	0.00	Rating **	A	Issue No.	5
LM End	0.00	Issue Type +	Ma	Location *	
Category	Pump Stations			GPS Latitude/Longitude	
				Start	End
Item	Safety			37.982317 °	37.982317 °
				-121.249433 °	-121.249433 °
DWR ID	DWR_NA0017_19_t_2012_5				
Action/Comments					
Inspector Comments: No safety hazard was found around the structure. All hand rails were in working condition.					

Photo 1 of 1 : ST_2018_NA0017_19_5_20180625_00018.jpg



View of the hand rails around the pumping plant.

LM Start	0.00	Rating **	N	Issue No.	6
LM End	0.00	Issue Type +	Ma	Location *	
Category	Pump Stations			GPS Latitude/Longitude	
				Start	End
Item	Cranes			37.982317 °	37.982317 °
				-121.249433 °	-121.249433 °
DWR ID	DWR_NA0017_19_t_2012_6				
Action/Comments					
Inspector Comments: No crane exists at this plant.					

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Structure 2018

San Joaquin County Flood Control and Water Conservation District

Structure	Structure Length	Inspection Start/End	Inspector
Mormon Slough Pumping Plant No. 2		06/21/2018 06/21/2018	Dave Torres

LM Start	0.00	Rating **	A	Issue No.	7
LM End	0.00	Issue Type +	Ma	Location *	
Category	Pump Stations			GPS Latitude/Longitude	
				Start	End
Item	Pumps			37.982317 °	37.982317 °
				-121.249433 °	-121.249433 °
DWR ID	DWR_NA0017_19_t_2012_7				
Action/Comments					
Inspector Comments: The pumps appeared to be well maintained and lubricated properly and the pumping system was tested periodically.					

Photo 1 of 2 : ST_2018_NA0017_19_7_20180625_00019.jpg



View of the pumps inside the pumping plant.

LM Start	0.00	Rating **	A	Issue No.	7 (cont)
LM End	0.00	Issue Type +	Ma	Location *	

Photo 2 of 2 : ST_2018_NA0017_19_7_20180530_00007.jpg



View of the shaft under a pump.

LM Start	0.00	Rating **	A	Issue No.	8
LM End	0.00	Issue Type +	Ma	Location *	
Category	Pump Stations			GPS Latitude/Longitude	
				Start	End
Item	Power			37.982317 °	37.982317 °
				-121.249433 °	-121.249433 °
DWR ID	DWR_NA0017_19_t_2012_8				
Action/Comments					
Inspector Comments: The power source appeared to be safe and reliable.					

Photo 1 of 1 : ST_2018_NA0017_19_8_20180625_00020.jpg



View of the power source used by the pumping plant.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Structure 2018

San Joaquin County Flood Control and Water Conservation District

Structure	Structure Length	Inspection Start/End	Inspector
Mormon Slough Pumping Plant No. 2		06/21/2018 06/21/2018	Dave Torres

LM Start	0.00	Rating **	A	Issue No.	10
LM End	0.00	Issue Type +	Ma	Location *	
Category	Pump Stations			GPS Latitude/Longitude	
				Start	End
Item	Motors, Engines, Fans & Gear Reducers			37.982317 °	37.982317 °
				-121.249433 °	-121.249433 °
DWR ID	DWR_NA0017_19_t_2012_10				
Action/Comments					
Inspector Comments: The vent fan was operational during the inspection.					

Photo 1 of 1 : ST_2018_NA0017_19_10_20180625_00022.jpg



View of the vent fan.

LM Start	0.00	Rating **	A	Issue No.	11
LM End	0.00	Issue Type +	Ma	Location *	
Category	Pump Stations			GPS Latitude/Longitude	
				Start	End
Item	Pump Control Systems			37.982317 °	37.982317 °
				-121.249433 °	-121.249433 °
DWR ID	DWR_NA0017_19_t_2012_11				
Action/Comments					
Inspector Comments: The pump control system is maintained and free of corrosion or any noticeable damage.					

Photo 1 of 1 : ST_2018_NA0017_19_11_20180625_00021.jpg



View of the power control system.

LM Start	0.00	Rating **	A	Issue No.	12
LM End	0.00	Issue Type +	Ma	Location *	
Category	Pump Stations			GPS Latitude/Longitude	
				Start	End
Item	Sumps/Wet Well			37.982317 °	37.982317 °
				-121.249433 °	-121.249433 °
DWR ID	DWR_NA0017_19_t_2012_12				
Action/Comments					
Inspector Comments: The wet well appeared to be clear of excessive debris or sediments.					

Photo 1 of 1 : ST_2018_NA0017_19_12_20180625_00023.jpg



View of the wet well.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Structure 2018

San Joaquin County Flood Control and Water Conservation District

Structure	Structure Length	Inspection Start/End	Inspector
Mormon Slough Pumping Plant No. 2		06/21/2018 06/21/2018	Dave Torres

LM Start	0.00	Rating **	A	Issue No.	13
LM End	0.00	Issue Type +	Ma	Location *	
Category	Pump Stations			GPS Latitude/Longitude	
				Start	End
Item	Trash Racks			37.982317 °	37.982317 °
				-121.249433 °	-121.249433 °
DWR ID	DWR_NA0017_19_t_2012_13				
Action/Comments					
Inspector Comments: Trash racks were properly maintained and free of any debris.					

Photo 1 of 1 : ST_2018_NA0017_19_13_20180625_00024.jpg



View of the trash racks.

LM Start	0.00	Rating **	N	Issue No.	14
LM End	0.00	Issue Type +	Ma	Location *	
Category	Pump Stations			GPS Latitude/Longitude	
				Start	End
Item	Trash Rakes			37.982317 °	37.982317 °
				-121.249433 °	-121.249433 °
DWR ID	DWR_NA0017_19_t_2012_14				
Action/Comments					
Inspector Comments: Trash rakes are not installed in this facility.					

No Photos

LM Start	0.00	Rating **	M	Issue No.	15
LM End	0.00	Issue Type +	Ma	Location *	
Category	Pump Stations			GPS Latitude/Longitude	
				Start	End
Item	Sluice / Slide Gates			37.982317 °	37.982317 °
				-121.249433 °	-121.249433 °
DWR ID	DWR_NA0017_19_t_2012_15				
Action/Comments					
Inspector Comments: The slide gate is not currently operational and requires repair.					

Photo 1 of 1 : ST_2018_NA0017_19_15_20180625_00025.jpg



View of the slide gate.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Structure 2018

San Joaquin County Flood Control and Water Conservation District

Structure	Structure Length	Inspection Start/End	Inspector
Mormon Slough Pumping Plant No. 2		06/21/2018 06/21/2018	Dave Torres

LM Start	0.00	Rating **	N	Issue No.	16
LM End	0.00	Issue Type +	Ma	Location *	
Category	Pump Stations			GPS Latitude/Longitude	
				Start	End
Item	Electric Gate Operators			37.982317 °	37.982317 °
				-121.249433 °	-121.249433 °
DWR ID	DWR_NA0017_19_t_2012_16				
Action/Comments					
Inspector Comments: This item was not present at this location.					

No Photos

LM Start	0.00	Rating **	A	Issue No.	17
LM End	0.00	Issue Type +	Ma	Location *	
Category	Pump Stations			GPS Latitude/Longitude	
				Start	End
Item	Manual Gate Operators			37.982317 °	37.982317 °
				-121.249433 °	-121.249433 °
DWR ID	DWR_NA0017_19_t_2012_17				
Action/Comments					
Inspector Comments: Manual gate appeared to be in good working condition. The wheel from the gate has been taken out for security purpose.					

No Photos

LM Start	0.00	Rating **	A	Issue No.	18
LM End	0.00	Issue Type +	Ma	Location *	
Category	Pump Stations			GPS Latitude/Longitude	
				Start	End
Item	Other Metallic Items			37.982317 °	37.982317 °
				-121.249433 °	-121.249433 °
DWR ID	DWR_NA0017_19_t_2012_18				
Action/Comments					
Inspector Comments: All the metal parts appeared to be in good condition.					

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Structure 2018

San Joaquin County Flood Control and Water Conservation District

Structure	Structure Length	Inspection Start/End	Inspector
Mormon Slough Pumping Plant No. 2		06/21/2018 06/21/2018	Dave Torres

LM Start	0.00	Rating **	A	Issue No.	19
LM End	0.00	Issue Type +	Ma	Location *	
Category	Pump Stations			GPS Latitude/Longitude	
				Start	End
Item	Flap Gates			37.982317 °	37.982317 °
				-121.249433 °	-121.249433 °
DWR ID	DWR_NA0017_19_t_2012_19				
Action/Comments					
Inspector Comments: Flap gates were in good condition and showed no damage. There was a lot of vegetation growth around the outlet, but the gates operation was not affected.					

Photo 1 of 1 : ST_2018_NA0017_19_19_20180625_00026.jpg



View of the flap gates for the pumping plant.

LM Start	0.00	Rating **	N	Issue No.	20
LM End	0.00	Issue Type +	Ma	Location *	
Category	Pump Stations			GPS Latitude/Longitude	
				Start	End
Item	Closure Structures			37.982317 °	37.982317 °
				-121.249433 °	-121.249433 °
DWR ID	DWR_NA0017_19_t_2012_20				
Action/Comments					
Inspector Comments: No closure structure was present at this plant.					

No Photos

LM Start	0.00	Rating **	A	Issue No.	21
LM End	0.00	Issue Type +	Ma	Location *	
Category	Pump Stations			GPS Latitude/Longitude	
				Start	End
Item	Security Fencing			37.982317 °	37.982317 °
				-121.249433 °	-121.249433 °
DWR ID	DWR_NA0017_19_t_2012_21				
Action/Comments					
Inspector Comments: Security fencing was in good condition without any damage.					

Photo 1 of 1 : ST_2018_NA0017_19_21_20180625_00027.jpg



View of the security fencing.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Structure 2018

San Joaquin County Flood Control and Water Conservation District

Structure	Structure Length	Inspection Start/End	Inspector
Mormon Slough Pumping Plant No. 2		06/21/2018 06/21/2018	Dave Torres

LM Start	0.00	Rating **	A	Issue No.	22
LM End	0.00	Issue Type +	Ma	Location *	
Category	Pump Stations			GPS Latitude/Longitude	
				Start	End
Item	Intake and Discharge Pipes			37.982317 °	37.982317 °
				-121.249433 °	-121.249433 °
DWR ID	DWR_NA0017_19_t_2013_22				
Action/Comments					
Inspector Comments: The pipes were free of any breaks, holes or cracks.					

No Photos

*** Location**
LS : Land Side
WS : Water Side
CR : Crown

**** Rating**
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

Flood Control Project Maintenance**Unit Cover Sheet****2018 Pumping Plant Inspection Results****San Joaquin County Flood Control and Water Conservation District**

Pumping Plant
Mormon Slough Pumping Plant No. 3

Pumping Plant Rating	A
Date of Inspection	6/21/2018
DWR Inspector	Dave Torres
Accompanied By	Jim Caruso San Joaquin County Channel Maintenance

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Structure 2018

San Joaquin County Flood Control and Water Conservation District

Structure	Structure Length	Inspection Start/End	Inspector
Mormon Slough Pumping Plant No. 3		06/21/2018 06/21/2018	Dave Torres

LM Start	0.00	Rating **	A	Issue No.	1
LM End	0.00	Issue Type +	Ma	Location *	
Category	Pump Stations			GPS Latitude/Longitude	
				Start	End
Item	Operating Log			37.973983 °	37.973983 °
				-121.229967 °	-121.229967 °
DWR ID	DWR_NA0017_20_t_2012_1				
Action/Comments					
Inspector Comments: Maintenance log was present at the pumping plant.					

Photo 1 of 1 : ST_2018_NA0017_20_1_20180625_00015.jpg



View of the operating log inside the plant.

LM Start	0.00	Rating **	A	Issue No.	2
LM End	0.00	Issue Type +	Ma	Location *	
Category	Pump Stations			GPS Latitude/Longitude	
				Start	End
Item	Operation & Maintenance Manual			37.973983 °	37.973983 °
				-121.229967 °	-121.229967 °
DWR ID	DWR_NA0017_20_t_2012_2				
Action/Comments					
Inspector Comments: The O&M Manual was present at the pumping plant next to the operating log.					

Photo 1 of 1 : ST_2018_NA0017_20_2_20180625_00016.jpg



View of the O&M manual inside the pumping plant.

LM Start	0.00	Rating **	A	Issue No.	3
LM End	0.00	Issue Type +	Ma	Location *	
Category	Pump Stations			GPS Latitude/Longitude	
				Start	End
Item	Plant Building			37.973983 °	37.973983 °
				-121.229967 °	-121.229967 °
DWR ID	DWR_NA0017_20_t_2012_3				
Action/Comments					
Inspector Comments: The plant building appeared to be in good structural condition.					

Photo 1 of 1 : ST_2018_NA0017_20_3_20180625_00017.jpg



View of the pumping plant.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Structure 2018

San Joaquin County Flood Control and Water Conservation District

Structure	Structure Length	Inspection Start/End	Inspector
Mormon Slough Pumping Plant No. 3		06/21/2018 06/21/2018	Dave Torres

LM Start	0.00	Rating **	A	Issue No.	4
LM End	0.00	Issue Type +	Ma	Location *	
Category	Pump Stations			GPS Latitude/Longitude	
				Start	End
Item	Communications			37.973983 °	37.973983 °
				-121.229967 °	-121.229967 °
DWR ID	DWR_NA0017_20_t_2012_4				
Action/Comments					
Inspector Comments: The district personnel carry cell phones and radios.					

No Photos

LM Start	0.00	Rating **	A	Issue No.	5
LM End	0.00	Issue Type +	Ma	Location *	
Category	Pump Stations			GPS Latitude/Longitude	
				Start	End
Item	Safety			37.973983 °	37.973983 °
				-121.229967 °	-121.229967 °
DWR ID	DWR_NA0017_20_t_2012_5				
Action/Comments					
Inspector Comments: No safety hazard was found around the pumping plant and guard rails around the plant were in a good condition.					

Photo 1 of 1 : ST_2018_NA0017_20_5_20180625_00018.jpg



View of the guard rails around the pumping plant.

LM Start	0.00	Rating **	N	Issue No.	6	
LM End	0.00	Issue Type +	Ma	Location *		
Category	Pump Stations			GPS Latitude/Longitude		
				Start	End	
Item	Cranes			37.973983 °	37.973983 °	
				-121.229967 °	-121.229967 °	
DWR ID	DWR_NA0017_20_t_2012_6					
Action/Comments						
Inspector Comments: There are no cranes in this plant.						

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Structure 2018

San Joaquin County Flood Control and Water Conservation District

Structure	Structure Length	Inspection Start/End	Inspector
Mormon Slough Pumping Plant No. 3		06/21/2018 06/21/2018	Dave Torres

LM Start	0.00	Rating **	A	Issue No.	7
LM End	0.00	Issue Type +	Ma	Location *	
Category	Pump Stations	GPS Latitude/Longitude			
		Start	End		
Item	Pumps	37.973983 °	37.973983 °		
		-121.229967 °	-121.229967 °		
DWR ID	DWR_NA0017_20_t_2012_7				
Action/Comments					
Inspector Comments: All pumps appeared to be in good condition and maintained properly.					

Photo 1 of 2 : ST_2018_NA0017_20_7_20180625_00019.jpg



View of the pumps inside the pumping plant.

LM Start	0.00	Rating **	A	Issue No.	7 (cont)
LM End	0.00	Issue Type +	Ma	Location *	

Photo 2 of 2 : ST_2018_NA0017_20_7_20180530_00006.jpg



View of bottom shaft of one of the pumps inside the plant.

LM Start	0.00	Rating **	A	Issue No.	8
LM End	0.00	Issue Type +	Ma	Location *	
Category	Pump Stations			GPS Latitude/Longitude	
				Start	End
Item	Power			37.973983 °	37.973983 °
				-121.229967 °	-121.229967 °
DWR ID	DWR_NA0017_20_t_2012_8				
Action/Comments					
Inspector Comments: The power source appeared to be safe and reliable.					

Photo 1 of 1 : ST_2018_NA0017_20_8_20180625_00020.jpg



View of the power source for the pumping plant.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Structure 2018

San Joaquin County Flood Control and Water Conservation District

Structure	Structure Length	Inspection Start/End	Inspector
Mormon Slough Pumping Plant No. 3		06/21/2018 06/21/2018	Dave Torres

LM Start	0.00	Rating **	A	Issue No.	10
LM End	0.00	Issue Type +	Ma	Location *	
Category	Pump Stations			GPS Latitude/Longitude	
				Start	End
Item	Motors, Engines, Fans & Gear Reducers			37.973983 °	37.973983 °
				-121.229967 °	-121.229967 °
DWR ID	DWR_NA0017_20_t_2012_10				
Action/Comments					
Inspector Comments: Pumping motors appeared to be operational and lubrication was maintained on all the pumps.					

No Photos

LM Start	0.00	Rating **	A	Issue No.	11
LM End	0.00	Issue Type +	Ma	Location *	
Category	Pump Stations			GPS Latitude/Longitude	
				Start	End
Item	Pump Control Systems			37.973983 °	37.973983 °
				-121.229967 °	-121.229967 °
DWR ID	DWR_NA0017_20_t_2012_11				
Action/Comments					
Inspector Comments: The pump control system appeared to be operational and free of damage.					

Photo 1 of 1 : ST_2018_NA0017_20_11_20180625_00021.jpg



View of the power control systems inside the plant.

LM Start	0.00	Rating **	A	Issue No.	12
LM End	0.00	Issue Type +	Ma	Location *	
Category	Pump Stations			GPS Latitude/Longitude	
				Start	End
Item	Sumps/Wet Well			37.973983 °	37.973983 °
				-121.229967 °	-121.229967 °
DWR ID	DWR_NA0017_20_t_2012_12				
Action/Comments					
Inspector Comments: Wet well was clear of any excessive debris.					

Photo 1 of 1 : ST_2018_NA0017_20_12_20180625_00022.jpg



View of wet well inside the pumping plant.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Structure 2018

San Joaquin County Flood Control and Water Conservation District

Structure	Structure Length	Inspection Start/End	Inspector
Mormon Slough Pumping Plant No. 3		06/21/2018 06/21/2018	Dave Torres

LM Start	0.00	Rating **	A	Issue No.	13	
LM End	0.00	Issue Type +	Ma	Location *		
Category	Pump Stations			GPS Latitude/Longitude		
				Start		End
Item	Trash Racks			37.973983 °		37.973983 °
				-121.229967 °		-121.229967 °
DWR ID	DWR_NA0017_20_t_2012_13					
Action/Comments						
Inspector Comments: The trash racks were free of any debris.						

Photo 1 of 1 : ST_2018_NA0017_20_13_20180625_00023.jpg



View of the trash racks.

LM Start	0.00	Rating **	N	Issue No.	14
LM End	0.00	Issue Type +	Ma	Location *	
Category	Pump Stations			GPS Latitude/Longitude	
				Start	End
Item	Trash Rakes			37.973983 °	37.973983 °
				-121.229967 °	-121.229967 °
DWR ID	DWR_NA0017_20_t_2012_14				
Action/Comments					
Inspector Comments: This item does not exist at this location.					

No Photos

LM Start	0.00	Rating **	A	Issue No.	15
LM End	0.00	Issue Type +	Ma	Location *	
Category	Pump Stations			GPS Latitude/Longitude	
				Start	End
Item	Sluice / Slide Gates			37.973983 °	37.973983 °
				-121.229967 °	-121.229967 °
DWR ID	DWR_NA0017_20_t_2012_15				
Action/Comments					
Inspector Comments: Slide gates appeared to be free of sediment and obstructions.					

Photo 1 of 1 : ST_2018_NA0017_20_15_20180625_00024.jpg



View of the slide gate.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Structure 2018

San Joaquin County Flood Control and Water Conservation District

Structure	Structure Length	Inspection Start/End	Inspector
Mormon Slough Pumping Plant No. 3		06/21/2018 06/21/2018	Dave Torres

LM Start	0.00	Rating **	N	Issue No.	16	
LM End	0.00	Issue Type +	Ma	Location *		
Category	Pump Stations			GPS Latitude/Longitude		
				Start	End	
Item	Electric Gate Operators			37.973983 °	37.973983 °	
				-121.229967 °	-121.229967 °	
DWR ID	DWR_NA0017_20_t_2012_16					
Action/Comments						
Inspector Comments: This item does not exist at this location.						

No Photos

LM Start	0.00	Rating **	A	Issue No.	17	
LM End	0.00	Issue Type +	Ma	Location *		
Category	Pump Stations			GPS Latitude/Longitude		
				Start	End	
Item	Manual Gate Operators			37.973983 °	37.973983 °	
				-121.229967 °	-121.229967 °	
DWR ID	DWR_NA0017_20_t_2012_17					
Action/Comments						
Inspector Comments: Manual gate appeared to be in good working condition. The wheel from the gate has been taken out for security purpose.						

No Photos

LM Start	0.00	Rating **	A	Issue No.	18
LM End	0.00	Issue Type +	Ma	Location *	
Category	Pump Stations			GPS Latitude/Longitude	
				Start	End
Item	Other Metallic Items			37.973983 °	37.973983 °
				-121.229967 °	-121.229967 °
DWR ID	DWR_NA0017_20_t_2012_18				
Action/Comments					
Inspector Comments: Other metallic parts within the pumping plant appeared to be in a good condition.					

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Structure 2018

San Joaquin County Flood Control and Water Conservation District

Structure	Structure Length	Inspection Start/End	Inspector
Mormon Slough Pumping Plant No. 3		06/21/2018 06/21/2018	Dave Torres

LM Start	0.00	Rating **	A	Issue No.	19
LM End	0.00	Issue Type +	Ma	Location *	
Category	Pump Stations			GPS Latitude/Longitude	
				Start	End
Item	Flap Gates			37.973983 °	37.973983 °
				-121.229967 °	-121.229967 °
DWR ID	DWR_NA0017_20_t_2012_19				
Action/Comments					
Inspector Comments: Flap gates were not visible during inspection due to water level.					

Photo 1 of 1 : ST_2018_NA0017_20_19_20180625_00025.jpg



View of the flap gates.

LM Start	0.00	Rating **	N	Issue No.	20	
LM End	0.00	Issue Type +	Ma	Location *		
Category	Pump Stations			GPS Latitude/Longitude		
				Start	End	
Item	Closure Structures			37.973983 °	37.973983 °	
				-121.229967 °	-121.229967 °	
DWR ID	DWR_NA0017_20_t_2012_20					
Action/Comments						
Inspector Comments: This item does not exist at this location.						

No Photos

LM Start	0.00	Rating **	M	Issue No.	21
LM End	0.00	Issue Type +	Ma	Location *	
Category	Pump Stations			GPS Latitude/Longitude	
				Start	End
Item	Security Fencing			37.973983 °	37.973983 °
				-121.229967 °	-121.229967 °
DWR ID	DWR_NA0017_20_t_2012_21				
Action/Comments					
Inspector Comments: Security fencing was damaged in one area near gate and requies repair.					

Photo 1 of 1 : ST_2018_NA0017_20_21_20180625_00026.jpg



View of the security fencing.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Structure 2018

San Joaquin County Flood Control and Water Conservation District

Structure	Structure Length	Inspection Start/End	Inspector
Mormon Slough Pumping Plant No. 3		06/21/2018 06/21/2018	Dave Torres

LM Start	0.00	Rating **	A	Issue No.	22
LM End	0.00	Issue Type +	Ma	Location *	
Category	Pump Stations			GPS Latitude/Longitude	
				Start	End
Item	Intake and Discharge Pipes			37.973983 °	37.973983 °
				-121.229967 °	-121.229967 °
DWR ID	DWR_NA0017_20_t_2012_22				
Action/Comments					
Inspector Comments: Pipes appeared to be in good condition.					

No Photos

*** Location**
LS : Land Side
WS : Water Side
CR : Crown

**** Rating**
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement